
CITY OF BALTIMORE WET SMOKE AND DYED I	Page 1 of 3				
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 08/26/2008			
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 04			
Manhole ID: S17I015MH	Test ID: 1029-601	Notifications Made:X Residents, Fire, 311			

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM						Page 2 of 3				
(Sewershed: Low Level Subsewershed: 44						Date: 08/26/2008			
	Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_				Supervisor: E.R. Crew: 04				
Ma	anhole ID: S17I015MH	Т	Test ID: 1029-601				Notifications Made:X Residents, Fire, 311			
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)										
Defect No.		Source Type			Drain Are	age			Photo N	Number
1	53 S. CATHERINE	09	14	02	0)	03		1029-601_C)B01-01.jpg
		OE	SERVAT	ION CO	DES					
	Source Type		Location			S	Sector		Sev	erity
01 Ma	ain Sewer 10 MH Frame	01 Paved	Conc. 10	Non-Pa	ved		Public	01	No Smoke	Ž
	ervice Line 11 Storm Drain	02 Asphalt			oods	02	Private		Trace	
	eanout 12 Catch Basin	03 Paved 0							Moderate	
	ownspout 13 Storm MH	04 Drivewa			urse			04	Major	
	ea Drain 14 Storm Ditch	05 Sidewa	lk 14	Other						
	vy. Drain 15 Excavation	06 Curb								
	air. Drain 16 Water Line	07 Yard - F			-			<u> </u>		
	und. Drai 17 Tele. Pole	08 Yard - E		1						
na Ric	dg. Interio 18 Other	09 Yard - S	oiae							

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 601 Date: 08/26/2008 Basin: LL - 44 Manhole ID: S17I__015MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 53 S. CATHERINE ST.

Source Type: 09 Building Interior Sector: 02 Private

Location: 14 Other Severity: 03 Moderate Drainage Area: 0

Comments: MODERATE AMOUNTS OF SMOKE ARE COMING FROM THE ABANDONED BUILDING AT THIS

ADDRESS.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-601_OB01-01.jpg